





Before



After



Before



After





Before



After

Before



After



Before



After





Chimney coming down in attic



Furnace flue vent dangerous



Small bathroom stained & drywall rotted



Flood light bulb too close to ceiling – fire hazard

Illegal wiring out of ceiling box - look at black overheated areas



Water lines covered by ½” black mold



Non operational water heater - gas line not code - burner roll out